


Aerial Construction Progress Documentation

Project: 7-Eleven - Charlotte, NC

Site Address: 4800 Prosperity Church Rd

Flight Date 12/07/25

Aerial overview




Primary Structure – Current Conditions



Front-left oblique

Fuel Station





Front-right oblique

Ladder to roof

Electrical room



Back of Primary Structure

Sidewalk Entrance

Site Work & Surrounding Areas



Fuel Price Sign

Asphalt Present in fueling area

Fuel Pump Signage



Electrical Room




Utility Room



Fueling area



Interior Progress Pictures



General Observations - Exterior

- 7-Eleven Signage present and turned on
- Fuel pumps present under Fuel canopy
- Fuel area/ Main parking lot has asphalt present
- Parking lines painted near main entrance
- Dumpster Area visible
- Stop line painted at site entry/exit

General Observations - Interior

- Signage for beverage area present
- Monitor is up behind the cashier counter and kitchen area
- Drink machines were present and turned on
- Self checkout island erected
- Shelf that holds soft drinks syrup installed

*Interior images are provided for visual documentation purposes only.

Documentation Summary

This report is part of a recurring aerial documentation schedule intended to provide consistent visual records of site conditions over time.